

EXTERNAL MOISTURE - ACCEPTABLE SOLUTION 1 (E2/AS1) MASONRY (DEC. 2011)

HEIGHT LIMITS - CONSTRUCTION OPTIONS

