
FIG. 66 WINDOW HEAD Brick Slips on Eterpan



manufacturers recommendation

Refer to www.ventclad.co.nz Detail no. VC.6.4.01 & 02